

---

---

**MUNICIPALITY OF KINCARDINE**

**BRIDGE OSIM REPORTS**

**2021**

**PEDESTRIAN STRUCTURES**

---

---



**MUNICIPALITY OF KINCARDINE**

**BRIDGE OSIM REPORTS**

**2021**

**PEDESTRIAN STRUCTURES**

October, 2021

**B. M. ROSS AND ASSOCIATES LIMITED**


Engineers and Planners  
62 North Street  
Goderich, ON N7A 2T4  
Phone: 519-524-2641  
Fax: 519-524-4403  
[www.bmross.net](http://www.bmross.net)

File No. 96038

**Summary Report:**



1-Facing South



Datum: NAD83 17N    Northing: 4890116    Easting: 448999

<b>Structure Name:</b> Stonehaven Pedestrian Bridge	<b>BMROSS File #:</b> BR1083	<b>MTO #:</b>	
<b>Main Hwy / Road #:</b>	<b>Bridge Condition Index (BCI):</b> 97	<b>CRV:</b> \$400,400	
<b>Road Name:</b> Yellow Trail		<b>Inspection Date:</b> 7/21/2021	
<b>Structure Location:</b> South of Kincardine Ave		<b>Next Inspection:</b> 8/20/2023	
<b>Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years	<b>Current Load Limit:</b> N/A	
<b>Overall Comments:</b> Half-through truss in good condition. Vegetation should be cut back.			

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Trusses/Arches	Cut back vegetation within 2.4m of bridge	1 to 5 yrs.	\$3,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	\$3,000

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text" value="Stonehaven Pedestrian Bridge"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Yellow Trail"/>	Northing: <input type="text" value="4890116"/>
Structure Location: <input type="text" value="South of Kincardine Ave"/>	Easting: <input type="text" value="448999"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Truss"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Half-Through Truss"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="45.0"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.71"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="76.95"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.5"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="3"/>	Bridge Condition Index: <input type="text" value="97"/>
Span Length(s): <input type="text" value="10"/> (m) <input type="text" value="25"/> (m) <input type="text" value="10"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text" value="BR1083"/>

**Historical Data:**

Year Built: <input type="text" value="2014"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>



Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Half-through truss in good condition. Vegetation should be cut back.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="77"/> (sq.m)
Replacement Cost: \$ <input type="text" value="400,400"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Trusses/Arches	Cut back vegetation within 2.4m of bridge	1 to 5 yrs.	\$3,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$3,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$3,000</b>

Justification:

Element Data:						
Element Group:	Abutments				Length:	0.61
Element Name:	Abutment Walls				Width:	2.4
Location:	N-S				Height:	1.28
Material:	Cast-in-place Concrete				Count:	2
Element Type:	Conventional Closed				Total Quantity:	6.1 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (6.1)				\$5,490	\$5,490
Comments:	Height: 1.28m (south), 1.80m (north)					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's				Length:	1.6
Element Name:	Floor Beams				Width:	0.051
Location:					Height:	0.102
Material:	Steel				Count:	42
Element Type:	Box/Trapezoidal				Total Quantity:	17.1 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (17.1)				\$7,182	\$7,182
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks				Length:	1.71
Element Name:	Deck Top - Thin Slab				Width:	45.0
Location:					Height:	
Material:	Wood				Count:	1
Element Type:	Wood Planks				Total Quantity:	77 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (77)			\$9,240	\$6,930
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P1

Element Data:						
Element Group:	Piers			Length:	0.61	
Element Name:	Shafts/Columns/Pile Bents			Width:	3.7	
Location:				Height:	1.8	
Material:	Cast-in-place Concrete			Count:	2	
Element Type:	Concrete Rectangular Columns			Total Quantity:	31 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (31)				\$27,900	\$27,900
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	45.0	
Element Name:	Bottom Chords			Width:	0.051	
Location:				Height:	0.051	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	13.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (13.8)				\$4,140	\$4,140
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:	Cut back vegetation within 2.4m of bridge.					
					Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	45.0	
Element Name:	Top Chords			Width:	0.051	
Location:				Height:	0.051	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	13.8 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (13.8)				\$4,140	\$4,140
Comments:	HSS 51x51x4.8					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P1

Element Data:						
Element Group:	Trusses/Arches			Length:	1.3	
Element Name:	Verticals/Diagonals			Width:	0.051	
Location:				Height:	0.051	
Material:	Steel			Count:	154	
Element Type:	Box/Trapezoidal			Total Quantity:	30.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (30.6)				\$9,180	\$9,180
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	





1-Facing South



2-West Elevation





3-Soffit



4-Steel Plates






Summary Report:



1-Facing South



Datum: NAD83 17N    Northing: 4890676    Easting: 449317

<b>Structure Name:</b> <input type="text" value="South Penetangore Bridge"/>	<b>BMROSS File #:</b> <input type="text" value="BR906"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="88"/>	<b>CRV:</b> <input type="text" value="\$650,000"/>
<b>Road Name:</b> <input type="text" value="Green Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="Between St. Albert St and Scott St"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="Repairs recommended"/> <b>Recommended Timing:</b> <input type="text" value="1-5 Years"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Half-through truss in good condition. Plate over expansion locations recommended."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Decks	Cover plates for expansion locations	1 to 5 yrs.	\$2,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$1,000
<b>Total</b>			<b>\$3,000</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text" value="South Penetangore Bridge"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Green Trail"/>	Northing: <input type="text" value="4890676"/>
Structure Location: <input type="text" value="Between St. Albert St and Scott St"/>	Easting: <input type="text" value="449317"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Truss"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Half-Through Truss"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="75.05"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.66"/> (m)	Skew Angle: <input type="text"/> (Degrees)
Total Struct. Area: <input type="text" value="124.583"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.5"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="4"/>	Bridge Condition Index: <input type="text" value="88"/>
Span Length(s): <input type="text" value="14.05"/> (m) <input type="text" value="36.1"/> (m) <input type="text" value="15.5"/> (m) <input type="text" value="9.4"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text" value="BR906"/>

**Historical Data:**

Year Built: <input type="text" value="2012"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:			
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023	
<b>Inspector:</b> Ryan Munn			
<b>Inspecting Firm:</b> BM Ross & Associates Limited			
<b>Others in Party:</b> Andrew McGarvey			
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain			
<b>Weather:</b> Sunny, Slight Breeze			
<b>Temperature:</b> 22 °C			

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Half-through truss in good condition. Plate over expansion locations recommended.	

Replacement Value:			
Structure Type:	<input style="width: 80%;" type="text" value="Bridge"/>	Structure Area:	<input style="width: 80%;" type="text" value="125"/> (sq.m)
Replacement Cost:	\$ <input style="width: 80%;" type="text" value="650,000"/>	Complexity Factor:	<input style="width: 80%;" type="text" value="1"/>
		Price per sq. m.:	\$ <input style="width: 80%;" type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>			

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Load carrying capacity</li> <li>02 Excessive deformations (deflections and rotations)</li> <li>03 Continuing settlement</li> <li>04 Continuing movements</li> <li>05 Seized bearings</li> </ul> | <ul style="list-style-type: none"> <li>06 Bearing not uniformly loaded/unstable</li> <li>07 Jammed expansion joint</li> <li>08 Pedestrian/vehicular hazard</li> <li>09 Rough riding surface</li> <li>10 Surface ponding</li> <li>11 Deck drainage</li> </ul> | <ul style="list-style-type: none"> <li>12 Slippery surfaces</li> <li>13 Flooding/channel blockage</li> <li>14 Undermining of foundation</li> <li>15 Unstable embankments</li> <li>16 Other</li> </ul> |
|---|--|---|

**Maintenance Needs**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Lift and Swing Bridge Maintenance</li> <li>02 Bridge Cleaning</li> <li>03 Bridge Handrail Maintenance</li> <li>04 Painting Steel Bridge Structures</li> <li>05 Bridge Deck Joint Repair</li> <li>06 Bridge Bearing Maintenance</li> </ul> | <ul style="list-style-type: none"> <li>07 Repair to Structural Steel</li> <li>08 Repair of Bridge Concrete</li> <li>09 Repair of Bridge Timber</li> <li>10 Bailey bridges - Maintenance</li> <li>11 Animal/Pest Control</li> <li>12 Bridge Surface Repair</li> </ul> | <ul style="list-style-type: none"> <li>13 Erosion Control at Bridges</li> <li>14 Concrete Sealing</li> <li>15 Rout and Seal</li> <li>16 Bridge Deck Drainage</li> <li>17 Scaling (Loose Concrete or ACR Steel)</li> <li>18 Other</li> </ul> |
|---|--|---|

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Decks	Cover plates for expansion locations	1 to 5 yrs.	\$2,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$2,000</b>

Associated Work Required:	
Mobilize / Demobilize	\$1,000
Approaches	\$0
Traffic Control / Detours	\$0
Utilities	\$0
Right of Way	\$0
Environmental Study	\$0
Engineering	\$0
Other	\$0
Contingencies	\$0
<b>Associated Work Sub-Total:</b>	
<b>\$1,000</b>	
<b>Total Cost:</b>	
<b>\$3,000</b>	

Justification:

Element Data:						
Element Group:	Abutments				Length:	0.56
Element Name:	Abutment Walls				Width:	2.35
Location:					Height:	0.5
Material:	Cast-in-place Concrete				Count:	2
Element Type:	Conventional Closed				Total Quantity:	2.35 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (2.35)				\$2,115	\$2,115
Comments:	Height varies.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's				Length:	1.65
Element Name:	Floor Beams				Width:	0.051
Location:					Height:	0.102
Material:	Steel				Count:	58
Element Type:	Box/Trapezoidal				Total Quantity:	24.4 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (24.4)			\$10,248	\$7,686
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	
Element Data:						
Element Group:	Decks				Length:	75.05
Element Name:	Deck Top - Thin Slab				Width:	1.66
Location:					Height:	
Material:	Wood				Count:	1
Element Type:	Wood Planks				Total Quantity:	124.6 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (124.6)			\$14,952	\$11,214
Comments:						
Performance Deficiencies:						
Recommended Work:	Cover plates to cover gaps between each span.					
					Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P2

Element Data:						
Element Group:	Piers			Length:	0.62	
Element Name:	Shafts/Columns/Pile Bents			Width:	2.85	
Location:				Height:	3.0	
Material:	Cast-in-place Concrete			Count:	3	
Element Type:	Concrete Rectangular Columns			Total Quantity:	62.5 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (62.5)				\$56,250	\$56,250
Comments:	Height varies.					
Performance Deficiencies:						
Recommended Work:						
				Recommended Timing:	None	
Maintenance needs:						
Maintenance work:				Maintenance Priority:		
Element Data:						
Element Group:	Trusses/Arches			Length:	75.05	
Element Name:	Bottom Chords			Width:	0.76	
Location:				Height:	0.76	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	34.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (34.2)			\$10,260	\$7,695
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:						
				Recommended Timing:	None	
Maintenance needs:						
Maintenance work:				Maintenance Priority:		
Element Data:						
Element Group:	Trusses/Arches			Length:	75.05	
Element Name:	Top Chords			Width:	0.076	
Location:				Height:	0.076	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	34.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (34.2)			\$10,260	\$7,695
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:						
				Recommended Timing:	None	
Maintenance needs:						
Maintenance work:				Maintenance Priority:		

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P2

Element Data:						
Element Group:	Trusses/Arches			Length:	1.3	
Element Name:	Verticals/Diagonals			Width:	0.051	
Location:				Height:	0.051	
Material:	Steel			Count:	200	
Element Type:	Box/Trapezoidal			Total Quantity:	39.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (39.8)			\$11,940	\$8,955
Comments:	Dimensions vary.					
Performance Deficiencies:						
Recommended Work:						
						Recommended Timing:
Maintenance needs:						
Maintenance work:					Maintenance Priority:	





1-Facing South



2-West Elevation






3-Soffit - North Span



Summary Report:



1-Facing East



Datum: NAD83 17N    Northing: 4890840    Easting: 449936

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text"/>	MTO #:	<input type="text"/>
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	<input type="text" value="75"/>	CRV:	<input type="text" value="\$88,400"/>
Road Name:	<input type="text" value="Red Trail"/>	Inspection Date:	<input type="text" value="7/21/2021"/>		
Structure Location:	<input type="text" value="Between Scott Street and Palmateer Drive (Helliwell Park)"/>		Next Inspection:	<input type="text" value="8/20/2023"/>	
Condition Summary:	<input type="text" value="No work identified"/>	Recommended Timing:	<input type="text"/>		
Overall Comments:	<input type="text" value="Steel beam bridge with wood deck in good condition."/>				
Current Load Limit:	<input type="text" value="N/A"/>				

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

Additional Investigations:

Maintenance Needs:

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4890840"/>
Structure Location: <input type="text" value="Between Scott Street and Palmateer Drive (Helliwell Pa"/>	Easting: <input type="text" value="449936"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="12.25"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.42"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="17.395"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.1"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="11.8"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Steel beam bridge with wood deck in good condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">17</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">88,400</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Load carrying capacity</li> <li>02 Excessive deformations (deflections and rotations)</li> <li>03 Continuing settlement</li> <li>04 Continuing movements</li> <li>05 Seized bearings</li> </ul> | <ul style="list-style-type: none"> <li>06 Bearing not uniformly loaded/unstable</li> <li>07 Jammed expansion joint</li> <li>08 Pedestrian/vehicular hazard</li> <li>09 Rough riding surface</li> <li>10 Surface ponding</li> <li>11 Deck drainage</li> </ul> | <ul style="list-style-type: none"> <li>12 Slippery surfaces</li> <li>13 Flooding/channel blockage</li> <li>14 Undermining of foundation</li> <li>15 Unstable embankments</li> <li>16 Other</li> </ul> |
|---|--|---|

**Maintenance Needs**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Lift and Swing Bridge Maintenance</li> <li>02 Bridge Cleaning</li> <li>03 Bridge Handrail Maintenance</li> <li>04 Painting Steel Bridge Structures</li> <li>05 Bridge Deck Joint Repair</li> <li>06 Bridge Bearing Maintenance</li> </ul> | <ul style="list-style-type: none"> <li>07 Repair to Structural Steel</li> <li>08 Repair of Bridge Concrete</li> <li>09 Repair of Bridge Timber</li> <li>10 Bailey bridges - Maintenance</li> <li>11 Animal/Pest Control</li> <li>12 Bridge Surface Repair</li> </ul> | <ul style="list-style-type: none"> <li>13 Erosion Control at Bridges</li> <li>14 Concrete Sealing</li> <li>15 Rout and Seal</li> <li>16 Bridge Deck Drainage</li> <li>17 Scaling (Loose Concrete or ACR Steel)</li> <li>18 Other</li> </ul> |
|---|--|---|

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Abutments				Length:	
Element Name:	Abutment Walls				Width:	1.84
Location:					Height:	0.56
Material:	Mass Concrete				Count:	2
Element Type:	Conventional Closed				Total Quantity:	2.1 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (2.1)			\$1,890	\$1,418
Comments:	Concrete blocks on both ends, east end almost completely buried.					
Performance Deficiencies:						
Recommended Work:						Recommended Timing:
Maintenance needs:						
Maintenance work:						Maintenance Priority:
Element Data:						
Element Group:	Approaches				Length:	
Element Name:	Wearing surface				Width:	
Location:					Height:	
Material:					Count:	
Element Type:					Total Quantity:	
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% ()				\$0
Comments:	Trail recently paved at both ends of bridge, two concrete retaining blocks installed at east end.					
Performance Deficiencies:						
Recommended Work:						Recommended Timing:
Maintenance needs:						
Maintenance work:						Maintenance Priority:
Element Data:						
Element Group:	Barriers				Length:	12.25
Element Name:	Railing Systems				Width:	0.09
Location:					Height:	1.17
Material:	Wood				Count:	2
Element Type:	Wood Rail >83mm thick on Wood Post				Total Quantity:	24.5 m
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (24.5)			\$2,450	\$1,838
Comments:						
Performance Deficiencies:						
Recommended Work:						Recommended Timing:
						None
Maintenance needs:						
Maintenance work:						Maintenance Priority:

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P3

Element Data:							
Element Group:	Beams/ML'E's			Length:	12.25		
Element Name:	Girders			Width:	0.14		
Location:				Height:	0.4		
Material:	Steel			Count:	2		
Element Type:	I-type			Total Quantity:	29.9 m2		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>		
Protection System:	None			BCI - Element Condition Values:			
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (29.9)			\$12,558	\$9,419	
Comments:							
Performance Deficiencies:							
Recommended Work:							
						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	
Element Data:							
Element Group:	Decks			Length:	12.25		
Element Name:	Deck Top - Thin Slab			Width:	1.42		
Location:				Height:			
Material:	Wood			Count:	1		
Element Type:	Wood Planks			Total Quantity:	17.4 m2		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>		
Protection System:	None			BCI - Element Condition Values:			
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (17.4)			\$2,088	\$1,566	
Comments:							
Performance Deficiencies:							
Recommended Work:							
						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	





1-Facing East




2-South Elevation





3-Soffit



4-Beams and West Abutment



5-North Elevation






**Summary Report:**



1-Facing South



Datum: NAD83 17N    Northing: 4892308    Easting: 450189

Structure Name: <input type="text"/>	BMROSS File #: <input type="text"/>	MTO #: <input type="text"/>
Main Hwy / Road #: <input type="text"/>	Bridge Condition Index (BCI): <input type="text" value="100"/>	CRV: <input type="text" value="\$62,400"/>
Road Name: <input type="text" value="Blue Trail"/>	Inspection Date: <input type="text" value="7/22/2021"/>	
Structure Location: <input type="text" value="Alps Park"/>	Next Inspection: <input type="text" value="8/20/2023"/>	
Condition Summary: <input type="text" value="No work identified"/>	Recommended Timing: <input type="text"/>	Current Load Limit: <input type="text" value="N/A"/>
Overall Comments: <input type="text" value="Twin CSP in excellent condition."/>		

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
Various	Associated Work		\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4892308"/>
Structure Location: <input type="text" value="Alps Park"/>	Easting: <input type="text" value="450189"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Culverts"/>	Surface Type: <input type="text" value="Gravel"/>
Structure Type: <input type="text" value="Round Culvert"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="2.6"/> (m)	Fill on Structure: <input type="text" value="0.4"/> (m)
Overall Str. Width: <input type="text" value="6.0"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="15.6"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="2.0"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="2"/>	Bridge Condition Index: <input type="text" value="100"/>
Span Length(s): <input type="text" value="1.2"/> (m) <input type="text" value="1.2"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text" value="2020"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Twin CSP in excellent condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Culvert</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">16</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">62,400</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">3,900.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Load carrying capacity</li> <li>02 Excessive deformations (deflections and rotations)</li> <li>03 Continuing settlement</li> <li>04 Continuing movements</li> <li>05 Seized bearings</li> </ul> | <ul style="list-style-type: none"> <li>06 Bearing not uniformly loaded/unstable</li> <li>07 Jammed expansion joint</li> <li>08 Pedestrian/vehicular hazard</li> <li>09 Rough riding surface</li> <li>10 Surface ponding</li> <li>11 Deck drainage</li> </ul> | <ul style="list-style-type: none"> <li>12 Slippery surfaces</li> <li>13 Flooding/channel blockage</li> <li>14 Undermining of foundation</li> <li>15 Unstable embankments</li> <li>16 Other</li> </ul> |
|---|--|---|

**Maintenance Needs**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Lift and Swing Bridge Maintenance</li> <li>02 Bridge Cleaning</li> <li>03 Bridge Handrail Maintenance</li> <li>04 Painting Steel Bridge Structures</li> <li>05 Bridge Deck Joint Repair</li> <li>06 Bridge Bearing Maintenance</li> </ul> | <ul style="list-style-type: none"> <li>07 Repair to Structural Steel</li> <li>08 Repair of Bridge Concrete</li> <li>09 Repair of Bridge Timber</li> <li>10 Bailey bridges - Maintenance</li> <li>11 Animal/Pest Control</li> <li>12 Bridge Surface Repair</li> </ul> | <ul style="list-style-type: none"> <li>13 Erosion Control at Bridges</li> <li>14 Concrete Sealing</li> <li>15 Rout and Seal</li> <li>16 Bridge Deck Drainage</li> <li>17 Scaling (Loose Concrete or ACR Steel)</li> <li>18 Other</li> </ul> |
|---|--|---|

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:



Element Data:						
Element Group:	Culverts			Length:	1.2	
Element Name:	Barrels			Width:	6.0	
Location:				Height:	1.2	
Material:	Plastic			Count:	2	
Element Type:	Pipe Round			Total Quantity:	45.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	Epoxy zinc/acrylic/acrylic			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (45.2)				\$15,820	\$15,820
Comments:	Polymer coated.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing South



2-South Barrel Facing East



3-North Barrel Facing East






Summary Report:



1-Facing East



Datum: NAD83 17N    Northing: 4891052    Easting: 449244

<b>Structure Name:</b> <input type="text" value="North Penetangore Bridge"/>	<b>BMROSS File #:</b> <input type="text" value="BR804"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="78"/>	<b>CRV:</b> <input type="text" value="\$348,400"/>
<b>Road Name:</b> <input type="text" value="Red Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="Geddes Park"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>
<b>Overall Comments:</b> <input type="text" value="Half-through truss in good condition."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text" value="North Penetangore Bridge"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4891052"/>
Structure Location: <input type="text" value="Geddes Park"/>	Easting: <input type="text" value="449244"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Truss"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Half-Through Truss"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="40.4"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.66"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="67.064"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.5"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="3"/>	Bridge Condition Index: <input type="text" value="78"/>
Span Length(s): <input type="text" value="18.2"/> (m) <input type="text" value="15.5"/> (m) <input type="text" value="6.7"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text" value="BR804"/>

**Historical Data:**

Year Built: <input type="text" value="2007"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>



Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Half-through truss in good condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">67</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">348,400</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Load carrying capacity</li> <li>02 Excessive deformations (deflections and rotations)</li> <li>03 Continuing settlement</li> <li>04 Continuing movements</li> <li>05 Seized bearings</li> </ul> | <ul style="list-style-type: none"> <li>06 Bearing not uniformly loaded/unstable</li> <li>07 Jammed expansion joint</li> <li>08 Pedestrian/vehicular hazard</li> <li>09 Rough riding surface</li> <li>10 Surface ponding</li> <li>11 Deck drainage</li> </ul> | <ul style="list-style-type: none"> <li>12 Slippery surfaces</li> <li>13 Flooding/channel blockage</li> <li>14 Undermining of foundation</li> <li>15 Unstable embankments</li> <li>16 Other</li> </ul> |
|---|--|---|

**Maintenance Needs**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Lift and Swing Bridge Maintenance</li> <li>02 Bridge Cleaning</li> <li>03 Bridge Handrail Maintenance</li> <li>04 Painting Steel Bridge Structures</li> <li>05 Bridge Deck Joint Repair</li> <li>06 Bridge Bearing Maintenance</li> </ul> | <ul style="list-style-type: none"> <li>07 Repair to Structural Steel</li> <li>08 Repair of Bridge Concrete</li> <li>09 Repair of Bridge Timber</li> <li>10 Bailey bridges - Maintenance</li> <li>11 Animal/Pest Control</li> <li>12 Bridge Surface Repair</li> </ul> | <ul style="list-style-type: none"> <li>13 Erosion Control at Bridges</li> <li>14 Concrete Sealing</li> <li>15 Rout and Seal</li> <li>16 Bridge Deck Drainage</li> <li>17 Scaling (Loose Concrete or ACR Steel)</li> <li>18 Other</li> </ul> |
|---|--|---|

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Abutments				Length:	0.55
Element Name:	Abutment Walls				Width:	2.15
Location:					Height:	1.13
Material:	Cast-in-place Concrete				Count:	2
Element Type:	Conventional Closed				Total Quantity:	4.9 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
	100% (4.9)				\$4,410	\$4,410
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks				Length:	40.4
Element Name:	Deck Top - Thin Slab				Width:	1.66
Location:					Height:	
Material:	Wood				Count:	1
Element Type:	Wood Planks				Total Quantity:	67.1 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (67.1)			\$8,052	\$6,039
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Piers				Length:	0.55
Element Name:	Shafts/Columns/Pile Bents				Width:	2.8
Location:					Height:	0.95
Material:	Cast-in-place Concrete				Count:	2
Element Type:	Concrete Rectangular Columns				Total Quantity:	12.7 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (12.7)			\$11,430	\$8,573
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P5

Element Data:						
Element Group:	Trusses/Arches			Length:	40.4	
Element Name:	Bottom Chords			Width:	0.076	
Location:				Height:	0.076	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	18.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (18.4)			\$5,520	\$4,140
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	40.4	
Element Name:	Top Chords			Width:	0.076	
Location:				Height:	0.076	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	18.4 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (18.4)			\$5,520	\$4,140
Comments:	Atmospheric corrosion resistant steel.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	1.5	
Element Name:	Verticals/Diagonals			Width:	0.05	
Location:				Height:	0.05	
Material:	Steel			Count:	68	
Element Type:	Box/Trapezoidal			Total Quantity:	15.3 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (15.3)			\$4,590	\$3,443
Comments:	Diagonals.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P5

Element Data:						
Element Group:	Trusses/Arches			Length:	1.04	
Element Name:	Verticals/Diagonals			Width:	0.05	
Location:				Height:	0.05	
Material:	Steel			Count:	70	
Element Type:	Box/Trapezoidal			Total Quantity:	10.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (10.9)			\$3,270	\$2,453
Comments:	Verticals.					
Performance Deficiencies:						
Recommended Work:						
						Recommended Timing:
Maintenance needs:						
Maintenance work:					Maintenance Priority:	





1-Facing East



2-South Elevation







3-Soffit



Summary Report:



1-Facing West



Datum: NAD83 17N    Northing: 4891966    Easting: 449632

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text" value="BR1258"/>	MTO #:	<input type="text"/>	
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	<input type="text" value="40"/>	CRV:	<input type="text" value="\$436,800"/>	
Road Name:	<input type="text" value="Blue Trail"/>	Inspection Date:	<input type="text" value="7/22/2021"/>			
Structure Location:	<input type="text" value="Between Princess St. and William St."/>		Next Inspection:	<input type="text" value="8/20/2023"/>		
Condition Summary:	<input type="text" value="Repairs recommended"/>	Recommended Timing:	<input type="text" value="Within 1 yr."/>		Current Load Limit:	<input type="text" value="N/A"/>
Overall Comments:	<input type="text" value="Multi-span steel beam bridge in fair condition. New decking in 2017 and protection of pier footings. Continue to monitor pier footings on each side of low flow channel and remove debris in channel."/>					

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Piers	Remove debris in channel	Within 1 yr.	\$3,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
			\$0
		<b>Total</b>	<b>\$3,000</b>

Additional Investigations:

Maintenance Needs:

Inventory Data:	
Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4891966"/>
Structure Location: <input type="text" value="Between Princess St. and William St."/>	Easting: <input type="text" value="449632"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="52.2"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.6"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="83.52"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.3"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="8"/>	Bridge Condition Index: <input type="text" value="40"/>
Span Length(s): <input type="text" value="52.2"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text" value="BR1258"/>

Historical Data:	
Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Rehabilitation / Investigation History:		
Year	Work Type	Cost
2017	New deck boards, protection of pier 3 footing (numbered from east end)	52000

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> Within 1 yr.
<b>Overall Comments:</b> Multi-span steel beam bridge in fair condition. New decking in 2017 and protection of pier footings. Continue to monitor pier footings on each side of low flow channel and remove debris in channel.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">84</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">436,800</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Piers	Remove debris in channel	Within 1 yr.	\$3,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$3,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$3,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	2.0	
Location:	E/W			Height:	0.3	
Material:	Cast-in-place Concrete			Count:	2	
Element Type:	Conventional Closed			Total Quantity:	1.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (1.2)		\$1,080	\$432
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Approaches			Length:		
Element Name:	Sidewalk			Width:		
Location:				Height:		
Material:				Count:	2	
Element Type:				Total Quantity:		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% ( )			\$0
Comments:	Concrete sidewalks at each end of the bridge.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	52.2	
Element Name:	Railing Systems			Width:	0.05	
Location:				Height:	1.08	
Material:	Steel			Count:	2	
Element Type:	Steel Post and Steel Panel			Total Quantity:	104.4 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (104.4)		\$20,880	\$8,352
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P6

Element Data:						
Element Group:	Beams/MLE's			Length:	52.2	
Element Name:	Girders			Width:	0.1	
Location:				Height:	0.2	
Material:	Steel			Count:	4	
Element Type:	I-type			Total Quantity:	146.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			90% (131.58)	10% (14.62)	\$61,404	\$22,105
Comments:	3 to 5 beams per span. Outside beams C-channels, middle beams are I-beams. Surface rust.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	52.2	
Element Name:	Deck Top - Thin Slab			Width:	1.5	
Location:				Height:	0.038	
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	78.3 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (78.3)			\$9,396	\$7,047
Comments:	Replaced in 2017. Spans (m): 4.8 (east), 7.0, 6.6, 8.8, 6.2, 6.9, 6.8, 5.1 (west).					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Piers			Length:	0.1	
Element Name:	Shafts/Columns/Pile Bents			Width:	1.6	
Location:				Height:	3.7	
Material:	Steel			Count:	7	
Element Type:	Steel Frame			Total Quantity:	88.1 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (88.1)		\$79,290	\$31,716
Comments:	Dimensions vary. Constructed from steel w-sections and angle iron.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P6

Element Data:						
<b>Element Group:</b>	Piers			<b>Length:</b>	1.5	
<b>Element Name:</b>	Shafts/Columns/Pile Bents			<b>Width:</b>	3.5	
<b>Location:</b>				<b>Height:</b>	3	
<b>Material:</b>	Cast-in-place Concrete			<b>Count:</b>	7	
<b>Element Type:</b>	Concrete Rectangular Columns			<b>Total Quantity:</b>	210 m2	
<b>Environment:</b>	Benign			<b>Limited / Not Inspected:</b>	<input type="checkbox"/>	
<b>Protection System:</b>	None			<b>BCI - Element Condition Values:</b>		
<b>Condition Data:</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>	<b>TEV</b>	<b>CEV</b>
			100% (210)		\$189,000	\$75,600
<b>Comments:</b>	Dimensions vary. Patch repaired piers 2 and 3 (numbered from east end). Underpinned pier 3 in 2017. Debris in channel.					
<b>Performance Deficiencies:</b>						
<b>Recommended Work:</b>	Remove debris from channel.					
					<b>Recommended Timing:</b>	< 1 year
<b>Maintenance needs:</b>						
<b>Maintenance work:</b>					<b>Maintenance Priority:</b>	





1-Facing West



2-South Elevation





3-Soffit



4-Middle Pier






5-North Elevation

Summary Report:



1-Facing East



Datum: NAD83 17N    Northing: 4892178    Easting: 449848

Structure Name: <input type="text"/>	BMROSS File #: <input type="text"/>	MTO #: <input type="text"/>
Main Hwy / Road #: <input type="text"/>	Bridge Condition Index (BCI): <input type="text" value="75"/>	CRV: <input type="text" value="\$98,800"/>
Road Name: <input type="text" value="Blue Trail"/>		Inspection Date: <input type="text" value="7/22/2021"/>
Structure Location: <input type="text" value="Mechanics Avenue"/>		Next Inspection: <input type="text" value="8/20/2023"/>
Condition Summary: <input type="text" value="Repairs recommended"/>	Recommended Timing: <input type="text" value="1-5 Years"/>	Current Load Limit: <input type="text" value="N/A"/>
Overall Comments: <input type="text" value="Steel beam bridge with steel grating in good condition."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Abutments	Erosion protection	1 to 5 yrs.	\$7,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$7,000</b>

Additional Investigations:

Maintenance Needs:

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4892178"/>
Structure Location: <input type="text" value="Mechanics Avenue"/>	Easting: <input type="text" value="449848"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Metal"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="14.7"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.32"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="19.404"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="11.6"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Steel beam bridge with steel grating in good condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">19</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">98,800</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Abutments	Erosion protection	1 to 5 yrs.	\$7,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$7,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$7,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	0.6	
Location:				Height:	0.25	
Material:	Cast-in-place Concrete			Count:	4	
Element Type:				Total Quantity:	0.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (0.6)			\$540	\$405
Comments:	Two concrete piers at either end, 600mm dia.					
Performance Deficiencies:						
Recommended Work:	Erosion protection.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	14.7	
Element Name:	Railing Systems			Width:		
Location:				Height:	1.32	
Material:	Steel			Count:	2	
Element Type:	Steel Post and Steel Panel			Total Quantity:	29.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (29.4)			\$5,880	\$4,410
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLÉ's			Length:	0.105	
Element Name:	Diaphragms			Width:	0.065	
Location:				Height:	0.25	
Material:	Steel			Count:	7	
Element Type:	I-type			Total Quantity:	7 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (7)			\$0	\$0
Comments:	C-channels.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P7

Element Data:						
Element Group:	Beams/MLE's			Length:	14.7	
Element Name:	Girders			Width:	0.14	
Location:				Height:	0.4	
Material:	Steel			Count:	2	
Element Type:	I-type			Total Quantity:	35.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (35.9)			\$15,078	\$11,309
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	14.7	
Element Name:	Deck Top - Thin Slab			Width:	1.32	
Location:				Height:		
Material:	Steel			Count:	1	
Element Type:				Total Quantity:	19.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (19.4)			\$2,328	\$1,746
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	





1-Facing East



2-North Elevation





3-Soffit




4-South Elevation



**Summary Report:**



1-Facing West



Datum: NAD83 17N    Northing: 4891464    Easting: 449765

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>	
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="62"/>	<b>CRV:</b> <input type="text" value="\$57,200"/>	
<b>Road Name:</b> <input type="text" value="Blue Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>		
<b>Structure Location:</b> <input type="text" value="Between Russell St. and Durham St."/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>		
<b>Condition Summary:</b> <input type="text" value="Repairs recommended"/> <b>Recommended Timing:</b> <input type="text" value="1-5 Years"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>		
<b>Overall Comments:</b> <input type="text" value="Wood bridge in fair condition. Bank protection recommended."/>			

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Abutments	Erosion protection	1 to 5 yrs.	\$10,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$10,000
<b>Total</b>			<b>\$20,000</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4891464"/>
Structure Location: <input type="text" value="Between Russell St. and Durham St."/>	Easting: <input type="text" value="449765"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="7.3"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.45"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="10.585"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="62"/>
Span Length(s): <input type="text" value="7.3"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Wood bridge in fair condition. Bank protection recommended.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">11</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">57,200</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Abutments	Erosion protection	1 to 5 yrs.	\$10,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$10,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$5,000
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$3,000
Other		\$0
Contingencies		\$2,000
<b>Associated Work Sub-Total:</b>		<b>\$10,000</b>
<b>Total Cost:</b>		<b>\$20,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:	0.14	
Element Name:	Abutment Walls			Width:	1.4	
Location:				Height:	0.14	
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	0.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (0.4)		\$360	\$144
Comments:	140x140 lumber. Banks are steep and eroded and should be protected with rip rap to maintain stability.					
Performance Deficiencies:						
Recommended Work:	Erosion protection.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	7.3	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.95	
Material:	Wood			Count:	2	
Element Type:	Wood Rail <83mm thick on Wood Post			Total Quantity:	14.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (14.6)		\$1,460	\$584
Comments:	Railings don't meet code for opening size, height or resistance.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	7.3	
Element Name:	Girders			Width:	0.08	
Location:				Height:	0.16	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	8.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (8.2)			\$1,640	\$1,230
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P8

Element Data:						
Element Group:	Decks			Length:	7.3	
Element Name:	Deck Top - Thin Slab			Width:	1.45	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	10.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (10.6)			\$1,272	\$954
Comments:						
Performance Deficiencies:						
Recommended Work:						
						Recommended Timing:
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing West




2-North Elevation






3-Soffit

**Summary Report:**



1-Facing North



Datum: NAD83 17N    Northing: 4889988    Easting: 448749

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>	
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="75"/>	<b>CRV:</b> <input type="text" value="\$83,200"/>	
<b>Road Name:</b> <input type="text" value="Yellow Trail"/>		<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="Between Bruce Ave. and Kincardine Ave."/>		<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Steel beam bridge with steel grating deck in good condition."/>			

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Yellow Trail"/>	Northing: <input type="text" value="4889988"/>
Structure Location: <input type="text" value="Between Bruce Ave. and Kincardine Ave."/>	Easting: <input type="text" value="448749"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Metal"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="12.7"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.23"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="15.621"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.1"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="10.3"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>



Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Steel beam bridge with steel grating deck in good condition.	

Replacement Value:			
Structure Type:	<input type="text" value="Bridge"/>	Structure Area:	<input type="text" value="16"/> (sq.m)
Replacement Cost:	\$ <input type="text" value="83,200"/>	Complexity Factor:	<input type="text" value="1"/>
		Price per sq. m.:	\$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>			

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Abutments				Length:	
Element Name:	Abutment Walls				Width:	1.83
Location:					Height:	0.82
Material:	Cast-in-place Concrete				Count:	2
Element Type:	Conventional Closed				Total Quantity:	3 m2
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (3)			\$2,700	\$2,025
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers				Length:	12.7
Element Name:	Railing Systems				Width:	
Location:					Height:	1.37
Material:	Steel				Count:	2
Element Type:	Steel Post and Steel Panel				Total Quantity:	25.4 m
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (25.4)			\$5,080	\$3,810
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/ML'E's				Length:	1.0
Element Name:	Diaphragms				Width:	
Location:					Height:	0.25
Material:	Steel				Count:	5
Element Type:	I-type				Total Quantity:	5 Each
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None				BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (5)			\$0	\$0
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P9

Element Data:							
Element Group:	Beams/MLE's			Length:	12.7		
Element Name:	Girders			Width:	0.14		
Location:				Height:	0.4		
Material:	Steel			Count:	2		
Element Type:	I-type			Total Quantity:	31 m2		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>		
Protection System:	None			BCI - Element Condition Values:			
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (31)			\$13,020	\$9,765	
Comments:							
Performance Deficiencies:							
Recommended Work:							
					Recommended Timing:	None	
Maintenance needs:							
Maintenance work:					Maintenance Priority:		
Element Data:							
Element Group:	Decks			Length:	1.23		
Element Name:	Deck Top - Thin Slab			Width:	12.7		
Location:				Height:			
Material:	Steel			Count:	1		
Element Type:				Total Quantity:	15.6 m2		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>		
Protection System:	None			BCI - Element Condition Values:			
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (15.6)			\$1,872	\$1,404	
Comments:							
Performance Deficiencies:							
Recommended Work:							
					Recommended Timing:	None	
Maintenance needs:							
Maintenance work:					Maintenance Priority:		





1-Facing North



2-West Elevation






3-Soffit




4-East Elevation

Summary Report:



1-Facing East



Datum: NAD83 17N    Northing: 4889533    Easting: 448270

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text"/>	MTO #:	<input type="text"/>
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	40	CRV:	\$223,600
Road Name:	Yellow Trail	Inspection Date:	7/21/2021		
Structure Location:	South of Bruce Ave.			Next Inspection:	8/20/2023
Condition Summary:	Repairs recommended	Recommended Timing:	1-5 Years		
Overall Comments:	Steel beam bridge with wood deck. Replace deteriorating deck boards.				
Current Load Limit:	N/A				

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Decks	Replace deteriorated deck boards	1 to 5 yrs.	\$3,000
Barriers	Improve railings	1 to 5 yrs.	\$2,000
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$5,000</b>

Additional Investigations:

Maintenance Needs:



**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Yellow Trail"/>	Northing: <input type="text" value="4889533"/>
Structure Location: <input type="text" value="South of Bruce Ave."/>	Easting: <input type="text" value="448270"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="14.96"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="2.88"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="43.0848"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="2.6"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="40"/>
Span Length(s): <input type="text" value="11.36"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Steel beam bridge with wood deck. Replace deteriorating deck boards.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">43</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">223,600</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Decks	Replace deteriorated deck boards	1 to 5 yrs.	\$3,000
Barriers	Improve railings	1 to 5 yrs.	\$2,000
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$5,000</b>

Associated Work Required:	
Right of Way	\$0
Environmental Study	\$0
Engineering	\$0
Other	\$0
Contingencies	\$0
Mobilize / Demobilize	\$0
Approaches	\$0
Traffic Control / Detours	\$0
Utilities	\$0
<b>Associated Work Sub-Total:</b>	
<b>\$0</b>	
<b>Total Cost:</b>	
<b>\$5,000</b>	

Justification:

Element Data:						
Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	3.25	
Location:				Height:	1.13	
Material:	Steel			Count:	2	
Element Type:				Total Quantity:	7.3 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (7.3)		\$6,570	\$2,628
Comments:	Double steel I-beam sections bolted to steel piles. Height varies.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	1.96	
Element Name:	Railing Systems			Width:		
Location:				Height:	0.96	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	3.9 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			70% (2.73)	30% (1.17)	\$390	\$109
Comments:	Cross member and handrails replaced recently. Some posts loose and rotting.					
Performance Deficiencies:						
Recommended Work:	Repair and improve railings.					
					Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/ML'E's			Length:	2.2	
Element Name:	Diaphragms			Width:		
Location:	End span			Height:	0.61	
Material:	Steel			Count:	2	
Element Type:	Cross Type			Total Quantity:	2 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (2)		\$0	\$0
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P10

Element Data:						
Element Group:	Beams/MLE's			Length:	0.74	
Element Name:	Diaphragms			Width:		
Location:	Mid span			Height:	0.46	
Material:	Steel			Count:	12	
Element Type:	Cross Type			Total Quantity:	12 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (12)		\$0	\$0
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	11.66	
Element Name:	Girders			Width:	0.26	
Location:				Height:	0.85	
Material:	Steel			Count:	4	
Element Type:	I-type			Total Quantity:	115.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (115.7)		\$48,594	\$19,438
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	2.88	
Element Name:	Deck Top - Thin Slab			Width:	14.96	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	43.1 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			90% (38.79)	10% (4.31)	\$5,172	\$1,862
Comments:	2x6 deck top resting on 10x10 timbers, resting on steel beams. Some rotting 2x6 boards on deck top.					
Performance Deficiencies:						
Recommended Work:	Replace deteriorating deck boards.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing East



2-North Elevation





3-Soffit




4-South Elevation



Summary Report:



1-Facing North



Datum: NAD83 17N    Northing: 4890158    Easting: 449340

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>	
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="40"/>	<b>CRV:</b> <input type="text" value="\$62,400"/>	
<b>Road Name:</b> <input type="text" value="Green Trail"/>		<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="North of Kincardine Ave."/>		<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="Repairs recommended"/>	<b>Recommended Timing:</b> <input type="text" value="1-5 Years"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Wood bridge in fair condition. Railing reinforcement recommended."/>			

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Barriers	Reinforce railings and adjust pier supports	1 to 5 yrs.	\$5,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$5,000</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Green Trail"/>	Northing: <input type="text" value="4890158"/>
Structure Location: <input type="text" value="North of Kincardine Ave."/>	Easting: <input type="text" value="449340"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Box Beams of Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="11"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.12"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="12.32"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="40"/>
Span Length(s): <input type="text" value="10"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Wood bridge in fair condition. Railing reinforcement recommended.	

Replacement Value:			
Structure Type:	<input type="text" value="Bridge"/>	Structure Area:	<input type="text" value="12"/> (sq.m)
Replacement Cost:	\$ <input type="text" value="62,400"/>	Complexity Factor:	<input type="text" value="1"/>
		Price per sq. m.:	\$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>			

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Barriers	Reinforce railings and adjust pier supports	1 to 5 yrs.	\$5,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$5,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$5,000</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	11.03	
Element Name:	Railing Systems			Width:		
Location:				Height:	1.0	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	22.1 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (22.1)		\$2,210	\$884
Comments:	Posts are piers that extend above deck. Railings don't meet code for height, opening size.					
Performance Deficiencies:						
Recommended Work:	Reinforce railings.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	11.3	
Element Name:	Girders			Width:	0.038	
Location:				Height:	0.184	
Material:	Wood			Count:	3	
Element Type:				Total Quantity:	33.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (33.9)		\$5,085	\$2,034
Comments:	2x8 dimension lumber beams.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	1.12	
Element Name:	Deck Top - Thin Slab			Width:	11.03	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	12.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (12.4)		\$1,488	\$595
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P11

Element Data:						
<b>Element Group:</b>	Piers			<b>Length:</b>	2.2	
<b>Element Name:</b>	Shafts/Columns/Pile Bents			<b>Width:</b>	0.09	
<b>Location:</b>				<b>Height:</b>	0.09	
<b>Material:</b>	Wood			<b>Count:</b>	18	
<b>Element Type:</b>				<b>Total Quantity:</b>	18 Each	
<b>Environment:</b>	Benign			<b>Limited / Not Inspected:</b>	<input type="checkbox"/>	
<b>Protection System:</b>	None			<b>BCI - Element Condition Values:</b>		
<b>Condition Data:</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>	<b>TEV</b>	<b>CEV</b>
			100% (18)		\$16,200	\$6,480
<b>Comments:</b>	4x4 wood posts resting on concrete base posts. Extend past deck to support railing.					
<b>Performance Deficiencies:</b>						
<b>Recommended Work:</b>	Monitor support conditions.				<b>Recommended Timing:</b>	1-5 years
<b>Maintenance needs:</b>						
<b>Maintenance work:</b>					<b>Maintenance Priority:</b>	



1-Facing North



2-West Elevation





3-Soffit




4-Pier

Summary Report:



1-Facing South



Datum: NAD83 17N    Northing: 4890561    Easting: 449562

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="4"/>	<b>CRV:</b> <input type="text" value="\$52,000"/>
<b>Road Name:</b> <input type="text" value="Green Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="Repairs recommended"/> <b>Recommended Timing:</b> <input type="text" value="1-5 Years"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Log beam bridge supporting wood decking. Bridge is in poor condition."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
	Reinforce structure, erosion protection	1 to 5 yrs.	\$20,000
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	\$20,000

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Green Trail"/>	Northing: <input type="text" value="4890561"/>
Structure Location: <input type="text"/>	Easting: <input type="text" value="449562"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Box Beams of Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="8.15"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.22"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="9.943"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="0.9"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="4"/>
Span Length(s): <input type="text" value="7"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>



Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Log beam bridge supporting wood decking. Bridge is in poor condition.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="10"/> (sq.m)
Replacement Cost: \$ <input type="text" value="52,000"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
	Reinforce structure, erosion protection	1 to 5 yrs.	\$20,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$20,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$20,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:	0.35	
Element Name:	Abutment Walls			Width:	1.5	
Location:				Height:	0.35	
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	1.1 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (1.1)	\$990	\$0
Comments:	Wood log abutments in deteriorated condition. Erosion occurring behind abutments.					
Performance Deficiencies:						
Recommended Work:	Reinforce structure, erosion protection.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Approaches			Length:	1.82	
Element Name:	Other			Width:	0.76	
Location:				Height:	0.038	
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	2.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (2.8)		\$0
Comments:	Dimension lumber approaches on concrete supports.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	8.15	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.94	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	16.3 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (16.3)	\$1,630	\$0
Comments:	Railings don't meet code for opening size, height or resistance.					
Performance Deficiencies:						
Recommended Work:	Reinforce structure.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P12

Element Data:						
Element Group:	Beams/MLE's			Length:	8.15	
Element Name:	Girders			Width:		
Location:				Height:		
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	16.3 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (16.3)	\$2,445	\$0
Comments:	200mm diameter log beams with a noticeable sag. Noticeable deflection in structure when walking.					
Performance Deficiencies:						
Recommended Work:	Reinforce structure.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	8.15	
Element Name:	Deck Top - Thin Slab			Width:	1.22	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	9.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			50% (4.95)	50% (4.95)	\$1,188	\$238
Comments:	Deck is uneven.					
Performance Deficiencies:						
Recommended Work:	Reinforce structure.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing South



2-West Elevation






3-Soffit

Summary Report:



1-Facing South



Datum: NAD83 17N    Northing: 4890591    Easting: 449608

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="75"/>	<b>CRV:</b> <input type="text" value="\$176,800"/>
<b>Road Name:</b> <input type="text" value="Green Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="Transition from Green to Red Trail"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>
<b>Overall Comments:</b> <input type="text" value="Aluminum seasonal bridge - installed in the spring and removed in the fall. Bridge is in good condition. Support condition should be monitored."/>		

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Green Trail"/>	Northing: <input type="text" value="4890591"/>
Structure Location: <input type="text" value="Transition from Green to Red Trail"/>	Easting: <input type="text" value="449608"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Composite"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="24.4"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.38"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="33.672"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.3"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="24.4"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum seasonal bridge - installed in the spring and removed in the fall. Bridge is in good condition. Support condition should be monitored.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">34</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">176,800</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	24.4	
Element Name:	Railing Systems			Width:	0.035	
Location:				Height:	0.96	
Material:	Aluminium			Count:	2	
Element Type:	Aluminum Post and Aluminum Panels			Total Quantity:	48.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (48.8)			\$9,760	\$7,320
Comments:	Railings don't meet code for opening size or weight.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	24.4	
Element Name:	Girders			Width:		
Location:				Height:	0.14	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	13.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (13.7)			\$2,740	\$2,055
Comments:	Beams rest on 12 posts.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	24.4	
Element Name:	Deck Top - Thin Slab			Width:	1.38	
Location:				Height:		
Material:	Aluminium			Count:	1	
Element Type:				Total Quantity:	33.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (33.7)			\$4,044	\$3,033
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing South



2-East Elevation





3-Soffit



4-West Elevation






**Summary Report:**



1-Facing West



Datum: NAD83 17N    Northing: 4890553    Easting: 449749

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="62"/>	<b>CRV:</b> <input type="text" value="\$78,000"/>
<b>Road Name:</b> <input type="text" value="Red Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>
<b>Overall Comments:</b> <input type="text" value="Aluminum girders supporting wood decking. Bridge is in fair to good condition."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4890553"/>
Structure Location: <input type="text"/>	Easting: <input type="text" value="449749"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="10.4"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.43"/> (m)	Skew Angle: <input type="text"/> (Degrees)
Total Struct. Area: <input type="text" value="14.872"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="62"/>
Span Length(s): <input type="text" value="7.4"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum girders supporting wood decking. Bridge is in fair to good condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">15</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">78,000</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	10.4	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.95	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	20.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (20.8)		\$2,080	\$832
Comments:	Railings don't meet code for height, opening size, or resistance.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	7.6	
Element Name:	Girders			Width:	0.08	
Location:				Height:	0.16	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	8.5 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (8.5)			\$1,700	\$1,275
Comments:	Girders appear to be supported on the stream banks.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	10.4	
Element Name:	Deck Top - Thin Slab			Width:	1.43	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	14.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (14.9)			\$1,788	\$1,341
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing West



2-North Elevation





3-Soffit



4-South Elevation






**Summary Report:**



1-Facing North



Datum: NAD83 17N    Northing: 4890398    Easting: 449860

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>	
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="75"/>	<b>CRV:</b> <input type="text" value="\$67,600"/>	
<b>Road Name:</b> <input type="text" value="Red Trail"/>		<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text"/>		<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Aluminum seasonal bridge - installed in the spring and removed in the fall. Bridge is in good condition. Support condition should be monitored."/>			

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Various	Associated Work		\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
		<b>Total</b>	\$0

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4890398"/>
Structure Location: <input type="text"/>	Easting: <input type="text" value="449860"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Composite"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="9.18"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.39"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="12.7602"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.3"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="9"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum seasonal bridge - installed in the spring and removed in the fall. Bridge is in good condition. Support condition should be monitored.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">13</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">67,600</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Approaches			Length:	4.75	
Element Name:	Other			Width:	1.21	
Location:	North End			Height:		
Material:	Wood			Count:	1	
Element Type:				Total Quantity:	5.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (5.7)				\$0
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	9.18	
Element Name:	Railing Systems			Width:	0.035	
Location:				Height:	0.97	
Material:	Aluminium			Count:	2	
Element Type:	Aluminum Post and Aluminum Panels			Total Quantity:	18.4 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (18.4)			\$3,680	\$2,760
Comments:	Railings don't meet code for height or opening size.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/ML'E's			Length:	9.18	
Element Name:	Girders			Width:	0.05	
Location:				Height:	0.14	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	5.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (5.6)			\$1,120	\$840
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P15

Element Data:						
Element Group:	Decks			Length:	9.18	
Element Name:	Deck Top - Thin Slab			Width:	1.39	
Location:				Height:		
Material:	Aluminium			Count:	1	
Element Type:				Total Quantity:	12.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (12.8)			\$1,536	\$1,152
Comments:						
Performance Deficiencies:						
Recommended Work:						
						Recommended Timing:
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing North




2-West Elevation






3-Soffit

Summary Report:



1-Facing North



Datum: NAD83 17N    Northing: 4889985    Easting: 449939

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="75"/>	<b>CRV:</b> <input type="text" value="\$109,200"/>
<b>Road Name:</b> <input type="text" value="Red Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="South End of Red Trail"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>
<b>Overall Comments:</b> <input type="text" value="Aluminum seasonal bridge - installed in the spring and removed in the fall. Bridge is in good condition. Support condition should be monitored."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4889985"/>
Structure Location: <input type="text" value="South End of Red Trail"/>	Easting: <input type="text" value="449939"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Composite"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="15.25"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.4"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="21.35"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.3"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="15.25"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text" value="2016"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum seasonal bridge - installed in the spring and removed in the fall. Bridge is in good condition. Support condition should be monitored.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">21</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">109,200</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Approaches			Length:	4.95	
Element Name:	Other			Width:	1.3	
Location:	South End			Height:	0.93	
Material:	Wood			Count:	1	
Element Type:				Total Quantity:	6.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (6.4)				\$0
Comments:	Wood deck approach with wood railing, slopes down toward bridge.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	15.25	
Element Name:	Railing Systems			Width:		
Location:				Height:	1.11	
Material:	Aluminium			Count:	2	
Element Type:	Aluminum Post and Aluminum Panels			Total Quantity:	30.5 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (30.5)			\$6,100	\$4,575
Comments:	Railings don't meet code for opening size.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/ML'E's			Length:	15.25	
Element Name:	Girders			Width:		
Location:				Height:	0.14	
Material:	Aluminium			Count:	2	
Element Type:	Rectangular-solid			Total Quantity:	8.5 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (8.5)			\$1,700	\$1,275
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

Element Data:						
Element Group:	Decks			Length:	15.25	
Element Name:	Deck Top - Thin Slab			Width:	1.4	
Location:				Height:		
Material:	Other			Count:	1	
Element Type:				Total Quantity:	21.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (21.4)			\$2,568	\$1,926
Comments:	Composite material deck top.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Piers			Length:		
Element Name:	Shafts/Columns/Pile Bents			Width:		
Location:				Height:	1.42	
Material:	Aluminium			Count:	8	
Element Type:				Total Quantity:	8 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (8)			\$7,200	\$5,400
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing North



2-East Elevation





3-Soffit




4-West Elevation



**Summary Report:**



1-Facing East



Datum: NAD83 17N    Northing: 4890382    Easting: 450135

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text"/>	MTO #:	<input type="text"/>	
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	40	CRV:	\$26,000	
Road Name:	Red Trail	Inspection Date:	7/21/2021			
Structure Location:	East End of Red Trail		Next Inspection:	8/20/2023		
Condition Summary:	No work identified	Recommended Timing:	<input type="text"/>		Current Load Limit:	N/A
Overall Comments:	Wood structure in fair condition.					

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4890382"/>
Structure Location: <input type="text" value="East End of Red Trail"/>	Easting: <input type="text" value="450135"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="4.94"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="0.96"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="4.7424"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="0.9"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="2"/>	Bridge Condition Index: <input type="text" value="40"/>
Span Length(s): <input type="text" value="2.5"/> (m) <input type="text" value="2.48"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Wood structure in fair condition.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="5"/> (sq.m)
Replacement Cost: \$ <input type="text" value="26,000"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	4.74	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	1.05	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	9.5 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (9.5)		\$950	\$380
Comments:	Railings don't meet code for opening size or resistance.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	4.74	
Element Name:	Stringers			Width:	0.038	
Location:				Height:	0.14	
Material:	Wood			Count:	3	
Element Type:	Rectangular-solid			Total Quantity:	3 Each	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (3)			\$0	\$0
Comments:	Appear to rest on banks.					
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	4.74	
Element Name:	Deck Top - Thin Slab			Width:	0.96	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	4.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (4.7)		\$564	\$226
Comments:						
Performance Deficiencies:						
Recommended Work:					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing East



2-North Elevation





3-Soffit



4-South Elevation






Summary Report:



1-Facing North



Datum: NAD83 17N    Northing: 4890712    Easting: 449925

Structure Name: <input type="text"/>	BMROSS File #: <input type="text"/>	MTO #: <input type="text"/>
Main Hwy / Road #: <input type="text"/>	Bridge Condition Index (BCI): <input type="text" value="50"/>	CRV: <input type="text" value="\$93,600"/>
Road Name: <input type="text" value="Red Trail"/>	Inspection Date: <input type="text" value="7/21/2021"/>	
Structure Location: <input type="text" value="North End of Red Trail"/>	Next Inspection: <input type="text" value="8/20/2023"/>	
Condition Summary: <input type="text" value="No work identified"/>	Recommended Timing: <input type="text"/>	Current Load Limit: <input type="text" value="N/A"/>
Overall Comments: <input type="text" value="Aluminum beams supporting wood decking in fair condition."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

Additional Investigations:

Maintenance Needs:

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4890712"/>
Structure Location: <input type="text" value="North End of Red Trail"/>	Easting: <input type="text" value="449925"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="12.3"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.43"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="17.589"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="50"/>
Span Length(s): <input type="text" value="7"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum beams supporting wood decking in fair condition.	

Replacement Value:			
Structure Type:	<input type="text" value="Bridge"/>	Structure Area:	<input type="text" value="18"/> (sq.m)
Replacement Cost:	\$ <input type="text" value="93,600"/>	Complexity Factor:	<input type="text" value="1"/>
		Price per sq. m.:	\$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>			

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:	0.14	
Element Name:	Abutment Walls			Width:	1.2	
Location:				Height:	0.28	
Material:	Wood			Count:	2	
Element Type:	Conventional Closed			Total Quantity:	0.67 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (0.67)		\$603	\$241
Comments:	2-140 x 140 wood boards at both ends.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	12.3	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.95	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	24.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (24.6)		\$2,460	\$984
Comments:	Railings don't meet code for opening size, height, or resistance.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	7.1	
Element Name:	Girders			Width:	0.085	
Location:				Height:	0.33	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	13 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (13)		\$2,600	\$1,040
Comments:	Additional height at midspan. Noticeable deflection when walking.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

# Ontario Structure Inspection Manual - Inspection Report:

Site Number: P18

Element Data:						
Element Group:	Decks			Length:	12.3	
Element Name:	Deck Top - Thin Slab			Width:	1.43	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	17.6 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (17.6)			\$2,112	\$1,584
Comments:	Tree at southeast corner.					
Performance Deficiencies:						
Recommended Work:						Recommended Timing:
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing North



2-West Elevation





3-Soffit




4-East Elevation

Summary Report:



1-Facing East



Datum: NAD83 17N    Northing: 4892402    Easting: 450389

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text"/>	MTO #:	<input type="text"/>	
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	58	CRV:	\$36,400	
Road Name:	Blue Trail	Inspection Date:	7/22/2021			
Structure Location:	89-North Line Extension		Next Inspection:	8/20/2023		
Condition Summary:	Repairs recommended	Recommended Timing:	1-5 Years		Current Load Limit:	N/A
Overall Comments:	Aluminum beams supporting wood deck. Bridge is in fair condition but supports should continue to be monitored.					

Repair / Rehabilitation:				
Element:	Work Required	Period	Cost	
Approaches	Re-align approaches	1 to 5 yrs.	\$6,000	
Barriers	Reinforce railings	1 to 5 yrs.	\$4,000	
			\$0	
			\$0	
			\$0	
			\$0	
			\$0	
Various	Associated Work		\$0	
		<b>Total</b>	<b>\$10,000</b>	

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4892402"/>
Structure Location: <input type="text" value="89-North Line Extension"/>	Easting: <input type="text" value="450389"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="4.87"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.41"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="6.8667"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.1"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="58"/>
Span Length(s): <input type="text" value="4.87"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>



Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Aluminum beams supporting wood deck. Bridge is in fair condition but supports should continue to be monitored.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="7"/> (sq.m)
Replacement Cost: \$ <input type="text" value="36,400"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Approaches	Re-align approaches	1 to 5 yrs.	\$6,000
Barriers	Reinforce railings	1 to 5 yrs.	\$4,000
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$10,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$10,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	1.2	
Location:				Height:	0.5	
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	1.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (1.2)		\$1,080	\$432
Comments:	Built up from dimension lumber and 140 x 140 wood.					
Performance Deficiencies:						
Recommended Work:	Monitor and stabilize.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Approaches			Length:	1.61	
Element Name:	Sidewalk			Width:	1.22	
Location:				Height:		
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (2)		\$120	\$48
Comments:	Out of alignment with deck.					
Performance Deficiencies:						
Recommended Work:	Re-align approaches.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	4.9	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.96	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	9.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (9.8)		\$980	\$392
Comments:	Railings don't meet code for height, resistance, or opening size.					
Performance Deficiencies:						
Recommended Work:	Reinforce railings.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

Element Data:							
Element Group:	Beams/ML'E's			Length:	4.87		
Element Name:	Girders			Width:	0.08		
Location:				Height:	0.165		
Material:	Aluminium			Count:	2		
Element Type:	I-type			Total Quantity:	7.2 m2		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>		
Protection System:	None			BCI - Element Condition Values:			
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (7.2)			\$1,440	\$1,080	
Comments:							
Performance Deficiencies:							
Recommended Work:							
						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	
Element Data:							
Element Group:	Decks			Length:	4.87		
Element Name:	Deck Top - Thin Slab			Width:	1.41		
Location:				Height:			
Material:	Wood			Count:	1		
Element Type:	Wood Planks			Total Quantity:	6.9 m2		
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>		
Protection System:	None			BCI - Element Condition Values:			
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (6.9)			\$828	\$621	
Comments:							
Performance Deficiencies:							
Recommended Work:							
						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	



1-Facing East



2-South Elevation






3-Soffit

**Summary Report:**



1-Facing South



Datum: NAD83 17N    Northing: 4892920    Easting: 451040

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text"/>	MTO #:	<input type="text"/>	
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	33	CRV:	\$78,000	
Road Name:	Blue Trail	Inspection Date:	7/22/2021			
Structure Location:	84-North Line Extension		Next Inspection:	8/20/2023		
Condition Summary:	Repairs recommended	Recommended Timing:	1-5 Years		Current Load Limit:	N/A
Overall Comments:	Log beam bridge supporting wood deck. Reinforcement recommended.					

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Beams/MLE's	Reinforcement recommended	1 to 5 yrs.	\$15,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$15,000</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4892920"/>
Structure Location: <input type="text" value="84-North Line Extension"/>	Easting: <input type="text" value="451040"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AA DT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Box Beams of Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="11.25"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.36"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="15.3"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.1"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="2"/>	Bridge Condition Index: <input type="text" value="33"/>
Span Length(s): <input type="text" value="3.65"/> (m) <input type="text" value="7.55"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Log beam bridge supporting wood deck. Reinforcement recommended.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="15"/> (sq.m)
Replacement Cost: \$ <input type="text" value="78,000"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Beams/MLE's	Reinforcement recommended	1 to 5 yrs.	\$15,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$15,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$15,000</b>

Justification:

Element Data:						
Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	1.8	
Location:				Height:	0.36	
Material:	Wood			Count:	2	
Element Type:	Conventional Closed			Total Quantity:	1.3 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (1.3)		\$1,170	\$468
Comments:	Built-up from 180 x 180 wood.					
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.			Recommended Timing:	1-5 years	
Maintenance needs:						
Maintenance work:				Maintenance Priority:		
Element Data:						
Element Group:	Barriers			Length:	11.25	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.97	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	22.5 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (22.5)		\$2,250	\$900
Comments:	Railings don't meet code for opening size, height, or resistance.					
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.			Recommended Timing:	1-5 years	
Maintenance needs:						
Maintenance work:				Maintenance Priority:		
Element Data:						
Element Group:	Beams/ML'E's			Length:	11.2	
Element Name:	Girders			Width:	0.2	
Location:				Height:	0.2	
Material:	Wood			Count:	2	
Element Type:	Rectangular-solid			Total Quantity:	13.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (13.4)	\$2,010	\$0
Comments:	200mm dia log beams with noticeable sag. Significant deflection felt when walking across deck.					
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.			Recommended Timing:	1-5 years	
Maintenance needs:						
Maintenance work:				Maintenance Priority:		

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P20

Element Data:						
Element Group:	Decks			Length:	11.25	
Element Name:	Deck Top - Thin Slab			Width:	1.36	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	15.3 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (15.3)		\$1,836	\$734
Comments:						
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.				Recommended Timing:	1-5 years
					Maintenance Priority:	
Maintenance needs:						
Maintenance work:						
Element Data:						
Element Group:	Piers			Length:	1.25	
Element Name:	Shafts/Columns/Pile Bents			Width:	1.25	
Location:				Height:	0.85	
Material:	Wood			Count:	1	
Element Type:				Total Quantity:	4.25 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (4.25)		\$3,825	\$1,530
Comments:	Pier is a timber crib filled with stones.					
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.				Recommended Timing:	1-5 years
					Maintenance Priority:	
Maintenance needs:						
Maintenance work:						



1-Facing South



2-East Elevation






3-Soffit

**Summary Report:**



1-Facing South



Datum: NAD83 17N    Northing: 4892898    Easting: 451106

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="28"/>	<b>CRV:</b> <input type="text" value="\$57,200"/>
<b>Road Name:</b> <input type="text" value="Blue Trail"/>	<b>Inspection Date:</b> <input type="text" value="7/22/2021"/>	
<b>Structure Location:</b> <input type="text" value="95-North Line Extension"/>	<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="Repairs recommended"/> <b>Recommended Timing:</b> <input type="text" value="1-5 Years"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Log beams supporting wood deck. Reinforcement recommended."/>		

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Beams/MLE's	Reinforce bridge and erosion protection	1 to 5 yrs.	\$20,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
<b>Total</b>			\$20,000

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4892898"/>
Structure Location: <input type="text" value="95-North Line Extension"/>	Easting: <input type="text" value="451106"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Box Beams of Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="8.0"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.4"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="11.2"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.1"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="28"/>
Span Length(s): <input type="text" value="8"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Log beams supporting wood deck. Reinforcement recommended.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="11"/> (sq.m)
Replacement Cost: \$ <input type="text" value="57,200"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Beams/MLE's	Reinforce bridge and erosion protection	1 to 5 yrs.	\$20,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$20,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$20,000</b>

Justification:

Element Data:						
Element Group:	Approaches			Length:	1.25	
Element Name:	Sidewalk			Width:	1.18	
Location:				Height:		
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	1.5 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (1.5)		\$90	\$36
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Barriers			Length:	8.0	
Element Name:	Railing Systems			Width:		
Location:				Height:	0.96	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	16 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (16)		\$1,600	\$640
Comments:	Openings and resistance don't meet code.					
Performance Deficiencies:						
Recommended Work:	Reinforce railings.					
					Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/ML'E's			Length:	8.0	
Element Name:	Girders			Width:	0.17	
Location:				Height:	0.17	
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	8.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (8.2)	\$1,230	\$0
Comments:	Log beams 170-250mm dia. Noticeable sag and deflection when walking on deck. Don't appear to rest on abutments.					
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.					
					Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

**Ontario Structure Inspection Manual - Inspection Report:**

Site Number: P21

Element Data:						
Element Group:	Decks			Length:	8.0	
Element Name:	Deck Top - Thin Slab			Width:	1.4	
Location:				Height:	0.038	
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	11.2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (11.2)		\$1,344	\$538
Comments:						
Performance Deficiencies:						
Recommended Work:	Reinforce bridge.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing South



2-West Elevation






3-Soffit

Summary Report:



1-Facing West



Datum: NAD83 17N    Northing: 4893741    Easting: 450080

<b>Structure Name:</b>	<input type="text"/>	<b>BMROSS File #:</b>	<input type="text"/>	<b>MTO #:</b>	<input type="text"/>
<b>Main Hwy / Road #:</b>	<input type="text"/>	<b>Bridge Condition Index (BCI):</b>	62	<b>CRV:</b>	\$36,400
<b>Road Name:</b>	Blue Trail	<b>Inspection Date:</b>	7/22/2021		
<b>Structure Location:</b>	West of Road 23		<b>Next Inspection:</b>	8/20/2023	
<b>Condition Summary:</b>	No work identified	<b>Recommended Timing:</b>	<input type="text"/>		
<b>Overall Comments:</b>	Wood beams supporting wood deck. Bridge is in fair condition.				
<b>Current Load Limit:</b>	N/A				

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4893741"/>
Structure Location: <input type="text" value="West of Road 23"/>	Easting: <input type="text" value="450080"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Box Beams of Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="4.91"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.5"/> (m)	Skew Angle: <input type="text"/> (Degrees)
Total Struct. Area: <input type="text" value="7.365"/> (sq.m)	Direction of Structure: <input type="text" value="East/West"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="62"/>
Span Length(s): <input type="text" value="4.9"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Wood beams supporting wood deck. Bridge is in fair condition.	

Replacement Value:			
Structure Type:	<span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area:	<span style="border: 1px solid black; padding: 2px;">7</span> (sq.m)
Replacement Cost:	\$ <span style="border: 1px solid black; padding: 2px;">36,400</span>	Complexity Factor:	<span style="border: 1px solid black; padding: 2px;">1</span>
		Price per sq. m.:	\$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>			

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	4.8	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.96	
Material:	Wood			Count:	2	
Element Type:	Wood Rail <83mm thick on Wood Post			Total Quantity:	9.6 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (9.6)		\$960	\$384
Comments:	Railings don't meet code requirements for opening size, height, or resistance.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	4.9	
Element Name:	Girders			Width:	0.14	
Location:				Height:	0.14	
Material:	Wood			Count:	2	
Element Type:	Rectangular-solid			Total Quantity:	4.1 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (4.1)		\$615	\$246
Comments:	140 x 140 wood beams. Don't appear to rest on abutments.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	4.91	
Element Name:	Deck Top - Thick Slab			Width:	1.5	
Location:				Height:	0.038	
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	7.4 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (7.4)			\$2,590	\$1,943
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1-Facing West



2-North Elevation





3-Soffit







**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Blue Trail"/>	Northing: <input type="text" value="4893923"/>
Structure Location: <input type="text" value="West End of Blue Trail"/>	Easting: <input type="text" value="449753"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Box Beams of Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="7.83"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.4"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="10.962"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="28"/>
Span Length(s): <input type="text" value="7.8"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> Repairs recommended	<b>Recommended Timing:</b> 1-5 Years
<b>Overall Comments:</b> Log beams supporting wood deck. Reinforcement recommended.	

Replacement Value:	
Structure Type: <input type="text" value="Bridge"/>	Structure Area: <input type="text" value="11"/> (sq.m)
Replacement Cost: \$ <input type="text" value="57,200"/>	Complexity Factor: <input type="text" value="1"/>
	Price per sq. m.: \$ <input type="text" value="5,200.00"/>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |                              |
|---|--|------------------------------|
| 01 Load carrying capacity                             | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 02 Excessive deformations (deflections and rotations) | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 03 Continuing settlement                              | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 04 Continuing movements                               | 09 Rough riding surface                  | 15 Unstable embankments      |
| 05 Seized bearings                                    | 10 Surface ponding                       | 16 Other                     |
|   | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                   | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance       | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures  | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Bridge Deck Joint Repair          | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance        | 12 Bridge Surface Repair        | 18 Other                                 |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
Beams/MLE's	Reinforcement recommended		\$15,000
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$15,000</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$15,000</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	7.8	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.95	
Material:	Wood			Count:	2	
Element Type:	Wood Rail <83mm thick on Wood Post			Total Quantity:	15.6 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (15.6)		\$1,560	\$624
Comments:	Railings don't meet code requirements for height, opening size, or resistance.					
Performance Deficiencies:						
Recommended Work:	Reinforcement recommended.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	7.8	
Element Name:	Girders			Width:	0.17	
Location:				Height:	0.17	
Material:	Wood			Count:	2	
Element Type:				Total Quantity:	8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
				100% (8)	\$1,200	\$0
Comments:	Log beams 170-240mm dia. Noticeable deflection when walking. Don't rest on abutments. Banks are steep.					
Performance Deficiencies:						
Recommended Work:	Reinforcement recommended.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	7.8	
Element Name:	Deck Top - Thin Slab			Width:	1.4	
Location:				Height:	0.038	
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	11 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (11)		\$1,320	\$528
Comments:						
Performance Deficiencies:						
Recommended Work:	Reinforcement recommended.				Recommended Timing:	1-5 years
Maintenance needs:						
Maintenance work:					Maintenance Priority:	



1 - Facing South



2 - West Elevation





3 - Soffit






**Summary Report:**



1-Facing North



Datum: NAD83 17N    Northing: 4899371    Easting: 451539

Structure Name: <input type="text"/>	BMROSS File #: <input type="text"/>	MTO #: <input type="text"/>
Main Hwy / Road #: <input type="text"/>	Bridge Condition Index (BCI): <input type="text" value="75"/>	CRV: <input type="text" value="\$405,600"/>
Road Name: <input type="text" value="Birchwood Ave. Trail"/>	Inspection Date: <input type="text" value="7/22/2021"/>	
Structure Location: <input type="text"/>	Next Inspection: <input type="text" value="8/20/2023"/>	
Condition Summary: <input type="text" value="No work identified"/>	Recommended Timing: <input type="text"/>	Current Load Limit: <input type="text" value="N/A"/>
Overall Comments: <input type="text" value="Half-through truss in good condition."/>		

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**

**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Birchwood Ave. Trail"/>	Northing: <input type="text" value="4899371"/>
Structure Location: <input type="text"/>	Easting: <input type="text" value="451539"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Truss"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="Half-Through Truss"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="36.5"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="2.13"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="77.745"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.8"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="75"/>
Span Length(s): <input type="text" value="36.5"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/22/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Half-through truss in good condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">78</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">405,600</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Load carrying capacity</li> <li>02 Excessive deformations (deflections and rotations)</li> <li>03 Continuing settlement</li> <li>04 Continuing movements</li> <li>05 Seized bearings</li> </ul>   | <ul style="list-style-type: none"> <li>06 Bearing not uniformly loaded/unstable</li> <li>07 Jammed expansion joint</li> <li>08 Pedestrian/vehicular hazard</li> <li>09 Rough riding surface</li> <li>10 Surface ponding</li> <li>11 Deck drainage</li> </ul>         | <ul style="list-style-type: none"> <li>12 Slippery surfaces</li> <li>13 Flooding/channel blockage</li> <li>14 Undermining of foundation</li> <li>15 Unstable embankments</li> <li>16 Other</li> </ul>                                       |
| <b>Maintenance Needs</b>  |  |   |
| <ul style="list-style-type: none"> <li>01 Lift and Swing Bridge Maintenance</li> <li>02 Bridge Cleaning</li> <li>03 Bridge Handrail Maintenance</li> <li>04 Painting Steel Bridge Structures</li> <li>05 Bridge Deck Joint Repair</li> <li>06 Bridge Bearing Maintenance</li> </ul> | <ul style="list-style-type: none"> <li>07 Repair to Structural Steel</li> <li>08 Repair of Bridge Concrete</li> <li>09 Repair of Bridge Timber</li> <li>10 Bailey bridges - Maintenance</li> <li>11 Animal/Pest Control</li> <li>12 Bridge Surface Repair</li> </ul> | <ul style="list-style-type: none"> <li>13 Erosion Control at Bridges</li> <li>14 Concrete Sealing</li> <li>15 Rout and Seal</li> <li>16 Bridge Deck Drainage</li> <li>17 Scaling (Loose Concrete or ACR Steel)</li> <li>18 Other</li> </ul> |



Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:							
Element Group:	Abutments				Length:		
Element Name:	Abutment Walls				Width:	2.7	
Location:					Height:	1.0	
Material:	Cast-in-place Concrete				Count:	2	
Element Type:	Conventional Closed				Total Quantity:	5.4 m2	
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None				BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (5.4)			\$4,860	\$3,645	
Comments:							
Performance Deficiencies:							
Recommended Work:						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	
Element Data:							
Element Group:	Barriers				Length:	36.5	
Element Name:	Railing Systems				Width:		
Location:					Height:	1.0	
Material:	Steel				Count:	2	
Element Type:	Steel Post and Steel Panel				Total Quantity:	73 m	
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None				BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (73)			\$14,600	\$10,950	
Comments:							
Performance Deficiencies:							
Recommended Work:						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	
Element Data:							
Element Group:	Beams/ML'E's				Length:	2.1	
Element Name:	Diaphragms				Width:	0.05	
Location:					Height:	0.15	
Material:	Steel				Count:	28	
Element Type:	Cross Type				Total Quantity:	28 Each	
Environment:	Benign				Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None				BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV	
		100% (28)			\$0	\$0	
Comments:							
Performance Deficiencies:							
Recommended Work:						Recommended Timing:	None
Maintenance needs:							
Maintenance work:						Maintenance Priority:	

Element Data:						
Element Group:	Decks			Length:	36.5	
Element Name:	Deck Top - Thin Slab			Width:	2.13	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	77.7 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (77.7)			\$9,324	\$6,993
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	36.5	
Element Name:	Bottom Chords			Width:	0.15	
Location:				Height:	0.15	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	32.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (32.9)			\$9,870	\$7,403
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	36.5	
Element Name:	Top Chords			Width:	0.15	
Location:				Height:	0.15	
Material:	Steel			Count:	2	
Element Type:	Box/Trapezoidal			Total Quantity:	32.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (32.9)			\$9,870	\$7,403
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	

Element Data:						
Element Group:	Trusses/Arches			Length:	1.28	
Element Name:	Verticals/Diagonals			Width:	0.1	
Location:	Outside Diagonals			Height:	0.15	
Material:	Steel			Count:	4	
Element Type:	Box/Trapezoidal			Total Quantity:	2 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (2)			\$600	\$450
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	1.5	
Element Name:	Verticals/Diagonals			Width:	0.07	
Location:	Inside Diagonals			Height:	0.05	
Material:	Steel			Count:	56	
Element Type:	Box/Trapezoidal			Total Quantity:	14.3 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (14.3)			\$4,290	\$3,218
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:					Maintenance Priority:	
Element Data:						
Element Group:	Trusses/Arches			Length:	1.18	
Element Name:	Verticals/Diagonals			Width:	0.1	
Location:	Verticals			Height:	0.1	
Material:	Steel			Count:	62	
Element Type:	Box/Trapezoidal			Total Quantity:	21.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (21.9)			\$6,570	\$4,928
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	
Maintenance needs:						
Maintenance work:					Maintenance Priority:	





1-Facing North



2-West Elevation






3-Soffit



Summary Report:



2-West Elevation



Datum: NAD83 17N    Northing: 4889555    Easting: 448290

<b>Structure Name:</b> <input type="text"/>	<b>BMROSS File #:</b> <input type="text"/>	<b>MTO #:</b> <input type="text"/>	
<b>Main Hwy / Road #:</b> <input type="text"/>	<b>Bridge Condition Index (BCI):</b> <input type="text" value="66"/>	<b>CRV:</b> <input type="text" value="\$57,200"/>	
<b>Road Name:</b> <input type="text" value="Yellow Trail"/>		<b>Inspection Date:</b> <input type="text" value="7/21/2021"/>	
<b>Structure Location:</b> <input type="text" value="South of Bruce Ave."/>		<b>Next Inspection:</b> <input type="text" value="8/20/2023"/>	
<b>Condition Summary:</b> <input type="text" value="No work identified"/>	<b>Recommended Timing:</b> <input type="text"/>	<b>Current Load Limit:</b> <input type="text" value="N/A"/>	
<b>Overall Comments:</b> <input type="text" value="Aluminum beams supporting wood deck in fair to good condition."/>			

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

**Additional Investigations:**

**Maintenance Needs:**



**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Yellow Trail"/>	Northing: <input type="text" value="4889555"/>
Structure Location: <input type="text" value="South of Bruce Ave."/>	Easting: <input type="text" value="448290"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="7.55"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.43"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="10.7965"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="66"/>
Span Length(s): <input type="text" value="4.4"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> Andrew McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum beams supporting wood deck in fair to good condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">11</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">57,200</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| 01 Load carrying capacity<br>02 Excessive deformations (deflections and rotations)<br>03 Continuing settlement<br>04 Continuing movements<br>05 Seized bearings | 06 Bearing not uniformly loaded/unstable<br>07 Jammed expansion joint<br>08 Pedestrian/vehicular hazard<br>09 Rough riding surface<br>10 Surface ponding<br>11 Deck drainage | 12 Slippery surfaces<br>13 Flooding/channel blockage<br>14 Undermining of foundation<br>15 Unstable embankments<br>16 Other |
|---|--|---|

**Maintenance Needs**

- |   |  |   |
|---|--|---|
| 01 Lift and Swing Bridge Maintenance<br>02 Bridge Cleaning<br>03 Bridge Handrail Maintenance<br>04 Painting Steel Bridge Structures<br>05 Bridge Deck Joint Repair<br>06 Bridge Bearing Maintenance | 07 Repair to Structural Steel<br>08 Repair of Bridge Concrete<br>09 Repair of Bridge Timber<br>10 Bailey bridges - Maintenance<br>11 Animal/Pest Control<br>12 Bridge Surface Repair | 13 Erosion Control at Bridges<br>14 Concrete Sealing<br>15 Rout and Seal<br>16 Bridge Deck Drainage<br>17 Scaling (Loose Concrete or ACR Steel)<br>18 Other |
|---|--|---|

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	7.55	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.96	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	15.1 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (15.1)			\$1,510	\$604
Comments:	Railings don't meet code requirements for height, opening size, resistance and they deflect under force.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	7.55	
Element Name:	Girders			Width:	0.08	
Location:				Height:	0.34	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	13.9 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (13.9)			\$2,780	\$2,085
Comments:	Beams taller at midspan. Beams rest on a bank at one end and lumber at the other end.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	7.55	
Element Name:	Deck Top - Thin Slab			Width:	1.43	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	10.8 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (10.8)			\$1,296	\$972
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	





1-Facing South



2-West Elevation






3-Soffit



Summary Report:



1-Facing West



Datum: NAD83 17N    Northing: 4890679    Easting: 449930

Structure Name:	<input type="text"/>	BMROSS File #:	<input type="text"/>	MTO #:	<input type="text"/>
Main Hwy / Road #:	<input type="text"/>	Bridge Condition Index (BCI):	50	CRV:	\$88,400
Road Name:	Red Trail	Inspection Date:	7/21/2021		
Structure Location:	North End of Red Trail		Next Inspection:	8/20/2023	
Condition Summary:	No work identified	Recommended Timing:	<input type="text"/>		
Overall Comments:	Aluminum beam bridge supporting wood deck in fair condition.				
<input type="text"/>					

Repair / Rehabilitation:

Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
Various	Associated Work		\$0
		<b>Total</b>	<b>\$0</b>

Additional Investigations:

Maintenance Needs:



**Inventory Data:**

Structure Name: <input type="text"/>	Crossing Type: <input type="text" value="Pedestrian"/>
Main Hwy / Road #: <input type="text"/>	On <input type="checkbox"/> Under <input type="checkbox"/>
Road Name: <input type="text" value="Red Trail"/>	Northing: <input type="text" value="4890679"/>
Structure Location: <input type="text" value="North End of Red Trail"/>	Easting: <input type="text" value="449930"/>
Owner(s): <input type="text" value="Municipality of Kincardine"/>	Heritage Designation: <input type="text"/>
MTO Region: <input type="text" value="Southwestern"/>	Road Class: <input type="text"/>
MTO District: <input type="text" value="Owen Sound"/>	Posted Speed: <input type="text"/> No. of Lanes: <input type="text"/>
Current County: <input type="text" value="Bruce"/>	AAADT: <input type="text" value="0-49"/> % Trucks: <input type="text"/>
Geographic Twp.: <input type="text" value="KINCARDINE"/>	Special Routes: <input type="text"/>
Structure Group: <input type="text" value="Beam/Girder"/>	Surface Type: <input type="text" value="Wood"/>
Structure Type: <input type="text" value="I-beam or Girders"/>	Detour Length Around Bridge: <input type="text"/> (km)
Total Deck Length: <input type="text" value="11.9"/> (m)	Fill on Structure: <input type="text" value="0"/> (m)
Overall Str. Width: <input type="text" value="1.43"/> (m)	Skew Angle: <input type="text" value="0"/> (Degrees)
Total Struct. Area: <input type="text" value="17.017"/> (sq.m)	Direction of Structure: <input type="text" value="North/South"/>
Roadway Width: <input type="text" value="1.2"/> (m)	Min. Vert. Clearance: <input type="text"/> (m)
Number of Spans: <input type="text" value="1"/>	Bridge Condition Index: <input type="text" value="50"/>
Span Length(s): <input type="text" value="7"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m) <input type="text"/> (m)	
MTO Number: <input type="text"/>	BMROSS File Number: <input type="text"/>

**Historical Data:**

Year Built: <input type="text"/>	Last Biennial Inspection: <input type="text" value="2020"/>
Current Load Limit: <input type="text"/> (tonnes)	Last Evaluation: <input type="text"/>
Load Limit By-Law #: <input type="text"/>	Last Enhanced Inspection: <input type="text"/>
By-Law Expiry Date: <input type="text"/>	Enhanced Access Equipment: <input type="text"/>

Field Inspection Information:		
<b>Date of Inspection:</b> 7/21/2021	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2023
<b>Inspector:</b> Ryan Munn		
<b>Inspecting Firm:</b> BM Ross & Associates Limited		
<b>Others in Party:</b> McGarvey		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny, Slight Breeze		
<b>Temperature:</b> 22 °C		

Additional Investigations			
Investigation Description	Note	Priority	Estimated Cost
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
<b>Total Cost:</b>			\$0

Overall Structure Notes:	
<b>Bridge Condition Summary:</b> No work identified	<b>Recommended Timing:</b>
<b>Overall Comments:</b> Aluminum beam bridge supporting wood deck in fair condition.	

Replacement Value:	
Structure Type: <span style="border: 1px solid black; padding: 2px;">Bridge</span>	Structure Area: <span style="border: 1px solid black; padding: 2px;">17</span> (sq.m)
Replacement Cost: \$ <span style="border: 1px solid black; padding: 2px;">88,400</span>	Complexity Factor: <span style="border: 1px solid black; padding: 2px;">1</span>
	Price per sq. m.: \$ <span style="border: 1px solid black; padding: 2px;">5,200.00</span>
<i>Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.</i>	

**Suspected Performance Deficiencies**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Load carrying capacity</li> <li>02 Excessive deformations (deflections and rotations)</li> <li>03 Continuing settlement</li> <li>04 Continuing movements</li> <li>05 Seized bearings</li> </ul> | <ul style="list-style-type: none"> <li>06 Bearing not uniformly loaded/unstable</li> <li>07 Jammed expansion joint</li> <li>08 Pedestrian/vehicular hazard</li> <li>09 Rough riding surface</li> <li>10 Surface ponding</li> <li>11 Deck drainage</li> </ul> | <ul style="list-style-type: none"> <li>12 Slippery surfaces</li> <li>13 Flooding/channel blockage</li> <li>14 Undermining of foundation</li> <li>15 Unstable embankments</li> <li>16 Other</li> </ul> |
|---|--|---|

**Maintenance Needs**

- |   |  |   |
|---|--|---|
| <ul style="list-style-type: none"> <li>01 Lift and Swing Bridge Maintenance</li> <li>02 Bridge Cleaning</li> <li>03 Bridge Handrail Maintenance</li> <li>04 Painting Steel Bridge Structures</li> <li>05 Bridge Deck Joint Repair</li> <li>06 Bridge Bearing Maintenance</li> </ul> | <ul style="list-style-type: none"> <li>07 Repair to Structural Steel</li> <li>08 Repair of Bridge Concrete</li> <li>09 Repair of Bridge Timber</li> <li>10 Bailey bridges - Maintenance</li> <li>11 Animal/Pest Control</li> <li>12 Bridge Surface Repair</li> </ul> | <ul style="list-style-type: none"> <li>13 Erosion Control at Bridges</li> <li>14 Concrete Sealing</li> <li>15 Rout and Seal</li> <li>16 Bridge Deck Drainage</li> <li>17 Scaling (Loose Concrete or ACR Steel)</li> <li>18 Other</li> </ul> |
|---|--|---|

Repair / Rehabilitation:			
Element:	Work Required	Period	Cost
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
			\$0
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$0</b>

Associated Work Required:		
Mobilize / Demobilize		\$0
Approaches		\$0
Traffic Control / Detours		\$0
Utilities		\$0
Right of Way		\$0
Environmental Study		\$0
Engineering		\$0
Other		\$0
Contingencies		\$0
<b>Associated Work Sub-Total:</b>		<b>\$0</b>
<b>Total Cost:</b>		<b>\$0</b>

Justification:

Element Data:						
Element Group:	Barriers			Length:	11.9	
Element Name:	Railing Systems			Width:	0.038	
Location:				Height:	0.95	
Material:	Wood			Count:	2	
Element Type:	Wood Rail >83mm thick on Wood Post			Total Quantity:	23.8 m	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (23.8)		\$2,380	\$952
Comments:	Railings don't meet code requirements for height, opening size, or resistance.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	
Element Data:						
Element Group:	Beams/MLE's			Length:	7.1	
Element Name:	Girders			Width:	0.085	
Location:				Height:	0.33	
Material:	Aluminium			Count:	2	
Element Type:	I-type			Total Quantity:	13 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
			100% (13)		\$2,600	\$1,040
Comments:	Beams taller at midspan. Rest on 140 x 140 lumber and banks. Noticeable deflection when walking on deck.					
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	
Element Data:						
Element Group:	Decks			Length:	11.9	
Element Name:	Deck Top - Thin Slab			Width:	1.43	
Location:				Height:		
Material:	Wood			Count:	1	
Element Type:	Wood Planks			Total Quantity:	17 m2	
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>	
Protection System:	None			BCI - Element Condition Values:		
Condition Data:	Excellent	Good	Fair	Poor	TEV	CEV
		100% (17)			\$2,040	\$1,530
Comments:						
Performance Deficiencies:						
Recommended Work:						
					Recommended Timing:	None
Maintenance needs:						
Maintenance work:						
					Maintenance Priority:	





1-Facing West



2-West Elevation





3-Soffit



4-East Elevation

